

These charts are a guideline with very close start points for trail riding with standard tires at low riding elevations.

X302 Recommended settings (PRO R CAM ARM) (choose the Crankshaft horsepower/Wheel horsepower that best matches your RZR)

Crankshaft horsepower (CHP) / Wheel horsepower (WHP)	Hole #1 (Closest to pin) Magnets	Hole #2 Magnets	Hole #3 (Tip of arm)Magnets	Sprgs	Full throttle RPM at 55mph
225CHP/190WHP Stock	1	4	0	OEM primary spring, KWI Black Orange secondary spring	8200 RPM +/-200 RPM or RPM SPECIFIED BY YOUR AFTERMARKET ENGINE TUNING SPECIALIST
250CHP/225WHP	2	4	2		
270CHP/240WHP	4	4	4		

X302T Recommended settings (PRO R T HEAVY CAM ARM) (choose the Crankshaft horsepower/Wheel horsepower that best matches your RZR)

Crankshaft horsepower (CHP) / Wheel horsepower (WHP)	Hole #1 (Closest to pin) Magnets	Hole #2 Magnets	Hole #3 (Tip of arm)Magnets	Sprgs	Full throttle RPM at 55mph
300CHP/280WHP	2	3	2	KWI Red primary spring, KWI Black Orange secondary spring	8400 RPM +/- 200 RPM or RPM SPECIFIED BY YOUR AFTERMARKET ENGINE TUNING SPECIALIST
350CHP/330WHP	5	5	5		